Duluth-Superior Area Truck Route Study



Committee Meeting August 2, 2018



Study Goal

Identify the most efficient, safest, and least disruptive truck route network within and through the Duluth-Superior area for the movement of goods and services via trucks, and support the inclusion of the identified network into local plans.


Agenda

- 1. Introductions
- 2. Update on Truck Counts
- 3. TRS Survey Results
- 4. Final TRS Report Topics
- 5. Next Steps / Action Items
- 6. Roundtable
- 7. Next Meeting


Truck Counts - Summary

- Provided By: Wisconsin DOT, St Louis & Carlton Counties
- 67 Locations
- All from 2016 and 2017
- Not Identical But Useable
- Hoping For Additional Truck Count and Accident Data
 - Douglas County
 - Minnesota DOT

Truck Count Locations




Truck Counts



Truck Counts

% Trucks

of Trucks



- ☐ ✓ Truck_Counts_2016_2017 No_Trucks
 - 0.000000 500.000000
 - 500.000001 1000.000000
 - 1000.000001 3000.000000
 - 3000.000001 8330.000000
- ☐ ▼ Truck_Counts_2016_2017
 Percent Trucks
 - 0.000000 5.000000
 - 5.000001 10.000000
 - 10.000001 15.000000
 - 15.000001 26.000000

Truck Counts - Data


Tabl	Table X														
°=	[- 1] - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -														
Truc	Truck_Counts_2016_2017 ×														
П	FID	Shape *	Site	ld	Site_id	Location	Municipali	No_Trucks	Tot_Traffi	No_Trucks1	Min_Ft	Max_Ft	date1	date2	A
F	58	Point	37B	0	0	Jean Duluth Road N of Glenwood Street	C of Duluth	0	0	0	0	0	August	2017	
	59	Point	37A	0	0	Snively Road E of CSAH 9 (Woodland Avenue)	C of Duluth	0	0	0	0	0	August	2017	
	21	Point	6A	0	0	Maple Grove Road E of CSAH 98 (Canosia Road)	Solway Township	22	338	6.5	0	0	October	2017	
	20	Point	56A	0	0	Morris Thomas Road E of TH 33		68	915	7.4	0	0	October	2017	
	36	Point	54B	0	0	Piedmont Avenue E of CSAH 56 (Morris Thomas Road)	C of Duluth	106	2501	4.2	0	0	July	2017	
	32	Point	56C	0		Morris Thomas Road E of CSAH 48 (Lavaque Road)	C of Hermantown	110	2921	3.8	0		July	2017	
	37	Point	56D	0		Morris Thomas Road E of CSAH 91 (Haines Road)	C of Duluth	118	3296	3.6	0		July	2017	
Щ	8	Point		0		Cnty E and Cnty Z	Parkland Township	128	2591	4.94	0		July	2015	
	19	Point	48A	0		Lavaque Road N of CR 696 (St. Louis River Road)	C of Proctor	142	2996	4.7	0		July	2017	
	60	Point	33A	0		McQuade Road N of TH 61	Lakewood Township	142	1136	12.5	0		August	2017	
	54	Point	44A	0		Normanna Road E of CSAH 4 (Rice Lake Road)		148	1557	9.5	0		October	2017	
	14	Point	3A	0		Becks Road E of Carlton County Line	Midway Township	151	908	16.6	0		June	2017	
	28	Point	56B	460272		Morris Thomas Road E of US 2	C of Hermantown	173	1483	11.7	0			2017	
	5	Point	160272 54A	160272		WI 13 just E of intersection with US 2/53	Parkland Township C of Duluth	183 230	3458 6490	5.292076	19		March	2017	
	39 49	Point Point	54A 90A	0		Piedmont Avenue E of CSAH 91 (Haines Road) Arlington Avenue N of US 53	C of Duluth	230	7022	3.5	0		July	2017	
╟┼	35	Point	91A	0		Haines Road N of Grand Avenue	C of Duluth	249	5074	4.9	0		July	2017	
Н	23	Point	98B	0		Canosia Road N of TH 194	Solway Township	259	1070	24.2	0		October	2017	
	38	Point	91B	0		Haines Road N of CSAH 56 (Morris Thomas Road)	Solway Township	292	7436	3.9	0		July	2017	
	34	Point	48C	0		Lavaque Road N of CSAH 6 (Maple Grove Road)	C of Hermantown	293	3440	8.5	0		July	2017	
	41	Point	6D	0		Maple Grove Road E of CSAH 91 (Haines Road)	C of Duluth	305	10964	2.8	0		July	2017	
	55	Point	37D	0		Jean Duluth Road N of CSAH 43 (Zimmerman Road)		311	2255	13.8	0		August	2017	=
	22	Point	98A	0		Canosia Road N of US 2	Solway Township	328	1330	24.7	0		October	2017	
	0	Point	160101	160101	160101	WI 35 N of Cnty B	Superior Township	347	5709	6.078122	19	200	March	2017	
	56	Point	43A	0	0	Zimmerman Road E of CSAH 37 (Jean Duluth Road)	Lakewood Township	350	1823	19.2	0	0	August	2017	
	18	Point	14A	0	0	Boundary Avenue N of I-35	C of Proctor	359	3661	9.8	0	0	July	2017	
	40	Point	91C	0	0	Haines Road N of CSAH 54 (Piedmont Avenue)		422	11150	3.8	0	0	July	2017	
	1	Point	160307	160307		WI 35 between 69th and 74th	V of Superior	432	11493	3.75881	19		March	2017	
Щ	30	Point	6B	0		Maple Grove Road E of CSAH 13 (Midway Road)	C of Hermantown	463	4470	10.4	0		June	2017	
	16	Point	13A	0		Midway Road S of I-35 Ramp	Midway Township	477	3996	11.9	0		June	2017	
	2	Point	160983	160983		Winter St just E of Maryland Ave	C of Superior	486	2928	16.598361	19		March	2017	
	15	Point	3B	0		Becks Road S of CSAH 13 (Midway Road)	Midway Township	512	4202	12.2	0		June	2017	
	42 53	Point	91D 9B	0		Haines Road N of CSAH 6 (Maple Grove Road) Martin Road E of CSAH 4 (Rice Lake Road)	O of Dioc Lobo	528 532	10110 5828	5.2 9.1	0		August	2017	
	31	Point Point	48B	0		Lavaque Road N of CSAH 56 (Morris Thomas Road)	C of Rice Lake C of Hermantown	566	3248	17.4	0		August	2017	
	52	Point	40D	0		Rice Lake Road N of CSAH 9 (Martin Road)	C of Rice Lake	680	6978	9.7	0		August	2017	
	24	Point	9A	0		Martin Road E of CSAH 13 (Midway Road)	Canosia Township	702	3087	22.7	0		August	2017	
	33	Point	6C	0		Maple Grove Road E of CSAH 48 (Lavague Road)	C of Hermantown	702	7269	9.7	0		June	2017	
	25	Point	13F	0		Midway Road N of US 53	Canosia Township	756	5201	14.5	0		August	2017	
	57	Point	37C	0		Jean Duluth Road N of CSAH 10 (Martin Road)	C of Duluth	799	6301	12.7	0		_	2017	
	48	Point	90B	0	0	Arlington Avenue N of TH 194	C of Duluth	858	10051	8.5	0	0	October	2017	
	26	Point	13E	0	0	Midway Road N of TH 194	C of Hermantown	871	4884	17.8	0	0	June	2017	
	45	Point	32A	0	0	Arrowhead Road E of US 53	C of Hermantown	953	12066	7.9	0	0		2017	
	43	Point	91E	0		Haines Road N of US 53		985	9018	10.9	0			2017	
	7	Point	160526	160526		US 2 Just W of Garfield roundabout	C of Superior	1094	16162	6.768964	29	200	March	2017	
	17	Point	13B	0		Midway Road N of I-35 Ramp	Midway Township	1207	7653	15.8	0		July	2017	
	47	Point	4B	0		Rice Lake Road N of CSAH 32 (Arrowhead Road)	C of Duluth	1256	10349	12.1	0		July	2017	
	50	Point	4A	0		Rice Lake Road N of TH 194	C of Duluth	1308	13584	9.6	0		August	2017	
	27 46	Point Point	13D 91F	0		Midway Road N of CSAH 6 (Maple Grove Road)	C of Hermantown	1381 1438	7080 8859	19.5 16.2	0		June October	2017	
	46	Point	160275	160275		Haines Road N of CSAH 32 (Arrowhead Road) US 53 just S of interesction with US 2	Amnicon Township	1650	12367	13.341958	19		March	2017	
	29	Point	13C	100275		Midway Road N of US 2	C of Hermantown	1855	9945	13.341936	0			2017	
H	•••		000		•		0 (0) "	2000	11000	10.7	-	-	···	2017	*
н	4	1	→ →1	(0 out	of 63 Select	ed)									
Tru	ck_C	ounts_2016_	2017												




Truck Route Study Survey Summary

- Purpose:
 - To seek input from those in the trucking industry or maintaining truck route roadways
 - In order to provide the most useful study recommendations possible
- 11 Questions + location-specific comment options
- Open February 21 April 30
- 42 People Responded

2018 Duluth-Superior Area Truck Route Study Survey							
What is your role in trucking? (check one)							
Answer Choices	Respo						
Truck driver	59.52%	25					
Warehousing	2.38%	1					
Trucking industry non-driver	28.57%	12					
Public Sector	9.52%	4					
Construction	23.81%	10					
Other (please specify)	2.38%	1					
	Answered	42					
	Skipped	0					




	Skipped	0		
	Answered	42	118	
Other (please specify)	21.43%	9		
Hazardous materials	11.90%	5		
Heavy haul loads	40.48%	17		
Oversize loads	42.86%	18		
Automobiles	4.76%	2		
Extended log trailer	0.00%	0		
Logs/lumber	14.29%	6		
Tanker (liquid or gas) trailers	19.05%	8		
Construction Materials	54.76%	23		
Flat bed	33.33%	14		
Extended freight trailer	0.00%	0		
Standard 53-foot trailer	38.10%	16		
Answer Choices	Respo	onses		
What do you pull and/or hau	I? (check al	ll that apply)	
2018 Duluth-Superior Are	a Truck Ro	oute Study	/ Survey	




2018 Duluth-Superior Area Truck Route Study Survey

Do you have any of the following concerns related to trucking regulations or their enforcement in the Duluth-Superior area? (check all that apply)

Answer Choices	Respo	onses	
No problems with regulations or enforcement	64.10%	25	
Regulations are difficult to find	12.82%	5	
Regulations are confusing or difficult to understand	15.38%	6	
Regulations between jurisdictions are not uniform	5.13%	2	
Regulations between trucking types are not consistent	7.69%	3	
Enforcement of regulations is not consistent	12.82%	5	
Enforcement penalties are too light (i.e., are not a deterrent)	5.13%	2	
Enforcement penalties are too severe	10.26%	4	
Permitting issues	10.26%	4	
Regulations are difficult to meet (explain):	0.00%	0	
	Answered	39	56
	Skipped	3	






2018 [2018 Duluth-Superior Area Truck Route Study Survey						
Are an	Are any traffic signal changes needed? (Note, you may also provide comment via interactive map)						
	Answer Choices	Response	. /				
No		85.71%	30				
Yes (des	cribe location and explain):	14.29%	5				
		Answered	35				
		Skipped	7				
	Are any tr	affic signal	changes				
	•	_	_	:i d a			
	needed? (No	•	-	ride			
	comment	via interact	tive map)				
90.00% -							
80.00% -							
70.00% -							
60.00%							
50.00%							
				Responses			
40.00% -				- Nesponses			
30.00% -							
20.00% -							
10.00% -							
0.00% -	0.00%						
	No Yes (describe location and explain):						

2018 Duluth-Superior Area Truck Route Stud	y Survey						
How common are the following roadway or infra	structure issu	ues along	truck rou	ites in the D	uluth-Superior a	rea? (Note, yo	ou may
also provide comme		_			•		·
	Not an iss	ue C	ommon and	d widespread	An issue in a spe	ecific location	Total
A. Road width — too narrow	71.43%	15	28.57%	6	0.00%		21
B. Shoulder width — too narrow	57.14%	12	42.86%	9	0.00%	-	21
C. Turning radius — too tight	56.52%	13	30.43%	7	13.04%	3	23
D. Resurfacing needed	30.00%	6	60.00%	12	10.00%	2	20
E. Regrading needed	65.00%	13	35.00%	7	0.00%	0	20
F. Turning lane needed	40.91%	9	50.00%	11	9.09%	2	22
G. Better water drainage needed	65.00%	13	35.00%	7	0.00%	0	20
H. Other — describe where and what, in text box below:	55.56%	5	33.33%	3	11.11%	1	9
Describe specific location(s) and needed improvements:							6
		86		62		8	
						Answered	24
						Skipped	18
How common are the fol	lowing roa	adway	or infra	astructui	re issues ald	ong	
truck routes in the Duluth	n-Superio	r area?	(Note	e vou ma	av also prov	⁄ide	
	•		`		•	140	
comments about a	specific id	ocalion	ı via ine	e interac	live map)		
80.00%							
70.00%							
60.00%							
50.00%							
40.00%					■ No	ot an issue	
30.00%					■ Co	mmon and widespr	ead
						'	
10.00% An issue in a specific location 0.00%						oca don	
A. Road width B. Shoulder C. Turning D. Resu	facing E. Regrad	ding F. Tur	ning lane G.	Better water	H. Other —		
— too narrow width — too radius — too need	0 0	U	eeded	drainage de	es cribe where		
narrow tight				needed a	and what, in		

text box below:

Q6 How common are the following roadway or infrastructure issues along truck routes in the Duluth-Superior area? (Note, you may also provide comments about a specific location via the interactive map)



Survey Results 6

n = 86, 62, 8 24 people

Resurfacing Needed &


Turning Lane Needed are only issues where the problem was rated greater than "not an issue"

2018 Duluth-Superior Area Truck Route Study Survey

If there is an especially problematic truck route segment or intersection in the Duluth-Superior area, please identify where it is. (Note, you may also provide comment via interactive map)


Answer Choices		Responses
LOCATION 1 (describe):	100.00%	9
	Answered	9
	Skipped	33
Respondents	Response Date	LOCATION 1 (describe):
1	May 08 2018 03:55 PM	Highway 61 North
2	May 08 2018 03:49 PM	Woodland Avenue and Arrowhead
3	May 08 2018 03:48 PM	Rice Lake Road and Martin Road
4	May 08 2018 12:12 PM	Arrowhead and 53 turning lanes for plowing. Island makes it difficult to plow and clean up.
5	Apr 17 2018 02:43 PM	MN194 and HWY 53
6	Apr 13 2018 10:37 AM	Tower to winter steet
7	Apr 12 2018 09:43 AM	l35 Tunnels
8	Mar 07 2018 10:10 PM	Can of Worms Intersection.
9	Mar 02 2018 02:01 PM	hwy 53 and E St. in Superior

2018 Duluth-Superior Area Truck Route Study Survey					
For location 1, above, what is the problem? (check all that apply)					
Answer Choices	Respo	onses			
Consistent congested traffic	40.00%	4			
Weight restrictions	0.00%	0			
Turns too tight	30.00%	3			
Inadequate turning lanes	50.00%	5			
Bridge height	10.00%	1			
Other (describe):	40.00%	4			
	Answered	10			
	Skipped	32			



2018 Duluth-Superior Area Truck Route Study Survey						
If there is another problematic truck route segment or intersection in the Duluth-Superior area, please identify where it is. (Note, you may also provide comment via interactive map)						
Answer Choices		Responses				
LOCATION 2 (describe):	100.00%	3				
	Answered	3				
	Skipped	39				
Respondents	Response Date	LOCATION 2 (describe):				
1	May 08 2018 03:48 PM	Highway 23				
2	Apr 17 2018 02:43 PM	Hwy 2 MN 194 intersection bridge				
3	Mar 02 2018 02:01 PM	solid railings at 535 entering l35 south bound				

2018 Duluth-Superior Area Truck Route Study Survey					
For location 2, above, what is the problem? (check all that apply)					
Answer Choices	Answer Choices Responses				
Consistent congested traffic	25.00%	1			
Weight restrictions	0.00%	0			
Turns too tight	0.00%	0			
Inadequate turning lanes	0.00%	0			
Bridge height	50.00%	2			
Other (describe):	50.00%	2			
	Answered	4			
	Skipped	38			



2018 Dulut	2018 Duluth-Superior Area Truck Route Study Survey						
Do you have	Do you have any other comments about truck routes in the Duluth-Superior area?						
Answered	3						
Skipped	39						
Respondents	Response Date	Responses					
1	Apr 17 2018 02:43 PM	More truck hauling signs near gravel Pits					
		Superior does a good job of labeling No Truck Routes. I only drive in a few parts of Duluth and have had no issues. I think the No Truck sign on Piedmont as you turn right from Superior Street could be placed before climbing up towards the bridge connecting it to US 53. Only done that in my car but the sign is only					
2	Mar 07 2018 10:14 PM	there once you are already in a residential area.					
3	Mar 02 2018 02:07 PM	none					

Summary of Survey Results

- Majority have no problem with regulations or enforcement
- No change to truck route signage needed
- Majority see no need for changes to traffic signals
- Two primary infrastructure-related issues:
 - Resurfacing needed
 - Turning lanes needed
- 16 site-specific suggestions



Final TRS Report Topics

- Introduction and Overview
- Current Conditions
 - Existing Positives
 - Concerns
- Map of Existing & Proposed Truck Routes
 - Truck Counts
 - Accidents Involving Trucks
- Recommendations
- Summary of Survey Responses

Primary Truck Route Study Contact

Mike Wenholz

MIC Senior Planner mwenholz@ardc.org 218-529-7573

